NON-FATA L ACCIDENTS/INCIDENTS: SCHEDULE D FLIGHT S

Date Carrier Aircraf t Locatio n

Injurie s
Crew Pass

Tota l
Occupant s
Crew Pass Phas e Circumstances

Jan 8

Jan 12

Jan 22

Jan 31

Feb 13

Feb 17

Feb 17

Feb 17

Feb 19

March 19

Apri l 8

May 1

May 7

Pakistan Inter- Boeing 720
national Airlines (AP-BAF)
Garuda

Malaysian Airline
System
Eastern Air
Lines
Indian Airlines

Philippine
Air Lines

Air California

British Airways

US A h

KLM

Eastern Air Lines

Far Eastern Air
Transport
Laker Airways

DC-10-30

(PK-GIB)

F.27

(9M-MCZ)
Boeina 727

Boeing 737

BA C One-Eleven
(RP-C1182)

Boeing 737
(N468AC)

Trident 3B
(G-AWZH)
DC-9

Boeing 747
(PH-BUM)
Boeing 727

Viscount
(B-2023)
A300

Quetta Airport,
Pakistan
Ujung Pandang
Airport, Sulawesi,
Indonesia
Kuala Lumpur

La Guardia Airport,
New York
Madras

Manila International
Airport

John Wayne
International Airport,
Santa An a

Luqa Airport, Malta

Greater Pittsburgh
International Airport,
Pennsylvania
Over North Sea

J.F.K. Airport,
New York
Semarang, Indonesia

En-route Lanzarote-

May 23 British Airways TriStar
(G-BBAH)
Pan A m 747

(N731PA)

June 3 Eastern Air Lines A300

June 16 Indian Airlines HS.748

June 16 Air India Boeing 747
June 19 Sudan Airways Boeing 707
(ST-AFB)
July 1 Guyana Airways HS.748
(8R-GEV)
July 23 British DC-10
Caledonian (G-BFGI)
Au g 10 British Airways Concorde
(G-BOAGJ
Au g 17 Pan A m Boeing 727
(N4742)
Au g 19 Indian Airlines HS.748
(VT-DXF)
Au g 19 Ethiopian Airlines DC-3
Au g 27 Ethiopian Airlines DC-3 (ET-AGX)
Sept 12 Toa Domestic DC-9
Airlines (JA-8427)
Sept 15 Korean Airlines Boeing 747
(HL.7447)
Sept 19 Zambia Airways HS.748
(9J-ABK)
Sept 19 Pan A m Boeing 747

Sept 21 Lesotho Airways Twin Ottei
(7P-LAB)
Sept 22 Eastern Air TriStar (N309EA)
Lines
Sept 24 Al l Nippon Boeing 737
Airway s
Sept 27 Zambia Airways HS.748
(9J-ADM)
Oct 7 Ethiopian Airlines DC-3 (ET-AHR)
Oct 13 Singapore Boeing 747
Airlines
Oct 20 ? Boeing 727
(5N-ANP)
Oct 21 Malev Tu-154
(HA-LCF)
Dec 7 Cruzeiro do Sul A300 (PP-CLA)

Dec 8 NLM Fokker F.27
(PH-KFD)
Dec 23 Eastern Air Lines ?
Dec 29 Eastern HS.748
Provincial
Airways

Gatwick

Heathrow Airport,
London

En route Florida-
Philadelphia
Tirupati, India

Ab u Dhabi Airport,
Jeddah

Georgetown

Kano

J. F. Kennedy Airport,
New York
Fort Lauderdale

Mangalore

Jimma
Diie Dawa

Haneda Airport, Tokyo —

Manila Int'l Airport

Ndola —

J. F. Kennedy Airport, —
New York

Lesotho —

J. F. Kennedy Airport —

Nagoya Airport —

Ndola —

Combolchia —
Perth Airport, —
Australia

Calabar —

Prague —

Pt Allegre —

Schiphol Airport, —
Amsterdam
Dorval Airport —
Sydney, Nova Scotia —

23

10

7

1

4

7

72

196

25

114

•7

•>

L

L

L

L

L

170

14

9

11

5

102

8

?

?

6

4

108

70

206

67

40

•>

T/O

T/O

ER~

L

L

ER

24

320

?

?

141

94

58

27

128

192

69

402

48
15

ER

C

L
G

T/O

RA

T/O

T/O

L

?

L

T/O

T/O

L

L

L

C

T/O

T/O

L
G

L

L

G

L

G
G

Nose landing gear failed

Ran off runway on landing. Substan-
tial damage

Right-hand main landing gear drag
strut failed
Right-hand main gear collapsed on
touch-down
Overrun runway with hydraulic system
failure
Struck ILS aerials causing engine
ingestion, but made safe emergency
landing
Aircraft skidded off runway

Aircraft aborted take-off with a No. 3
engine fire
Used 1,000ft of unprepared ground
beyond runway for take-off run.
Sustained minor tail damage
Returned to Schiphol after extinguish-
ing No. 1 engine fire
Made gear-up landing following port
main undercarriage failure
Ran off runway. Right main and nose
landing gear collapsed
Port engine failed. Aircraft diverted to
Las Palmas for a single-engine
landing
Wingtip damage caused in taxiing
collision

Turbulence

Crashed-landed, possibly because of
windshear
Engine cowling detached
Ran into rainwater ditch while taxiing

Crashed. Damaged nose and propel-
lers
Aquaplaned and overran runway

Blew seven tyres aborting take-off

Landing gear collapsed and aircraft
skidded off runway
Overran runway in bad weather

Birdstrike damaged wing
Tyre burst on landing, swung off run-
way
No. 1 engine failure. Suspected
foreign object damage
Overran runway and hit fence

Reported hydraulic failure. Veered off
runway and hit building
Piece of wing flap detached

Heavy landing caused nose gear
collapse
Uncontained No. 2 engine failure.
Substantial damage to control runs
Both engines damaged by birdstrike.
T/O aborted
Starboard engine fire during take-off.
T/O aborted
Undercarriage collapsed
Nosewheel bogged during taxiing

Bad weather diversion from Enugu to
Calabar. Overran runway
Badly damaged on landing. No fur-
ther details
Nose landing gear collapsed when
aircraft swung off runway
Main landing gear collapsed on
landing
Slid off runway in snowstorm
Hit terminal building while taxiing in

T/ O Take-off; C Climb; ER En route; A A Airfield approach; R A Runway approach; L Landing; G On ground.

FLIGHT International, 23 January 1982 185